Annexure D

BUILDING SAFETY CERTIFICATE

No.CAMP/AE/1895/26-27/FTP **Dated: 05/05/2026**

It is certified that the existing building **The Oak Public School** (name of the building or premises) at **109, Kalpana Bhawan, Collector Ganj, Fatehpur, Uttar Pradesh- 212601** (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	**G+2**					

The building is owned/occupied by **The Oak Public School** (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of **PWD CD-02, Fatehpur**, (Name of Department/ Govt.) on 05/05/2026 (date of inspection) in the presence of **Rohitabh Solanki, Kalpana Bhawan, Collector Ganj, Fatehpur, Uttar Pradesh-212601**(name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from **05/05/2026** for a period of **05** years in accordance with rule and subject to compliance of the specific conditions as appended.

1.
2.
3.
4.

Issued on **05/05/2026** at **FATEHPUR** by

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal : 05/05/26

Name : D.K. Arya

Designation : J.E. (Civil) C.D.2, P.W.D. Fatehpur

Name & Address of Department/ Office: _____

The Oak Public School Principal

The Oak Public School Rohitabh Solanki Manager